

Contacting Technical Support

Phone:

866.838.5052

Email:

For SnapAV customers, snapav.com

Firmware Release 3/26/2019 Details

Affected Sku	Driver Revision
AU-MMS-1e	6.1.6
AU-MMS-3e	6.1.6
AU-MMS-5e	6.1.6

Changes in this Release

1. Improve handling of secondary Wolfpack member power cycle
2. Improve logging instance driver
3. Improve handling of instance drivers connected to secondary Wolfpack members
4. Improve eAudioCast support
5. Monitor server socket state and rebuild if socket in broken state
6. Properly remove all broadcast audio stations on driver removal

Firmware Release 4/12/2018 Details

Affected Sku	Driver Revision
AU-MMS-1e	6.0.3
AU-MMS-3e	6.0.3
AU-MMS-5e	6.0.3

Changes in this Release

1. Amazon Music Support
2. MMS instances available for selection after MCP restart (or director restart)
3. Local music driver navigation fix for browsing all songs by an artist
4. Local music driver playing all songs by an artist